

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

JH1335
NNW
> 1
1.697 mi.
8959 ft.

MANHOLE 6875
BAY PARKWAY/86ST STREET
BROOKLYN, NY

NY Spills S104651699
N/A

Site 5 of 5 in cluster JH

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: MANHOLE 6875
Address: BAY PARKWAY/86ST STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0000395 / 2002-01-17
Facility ID: 0000395
Facility Type: ER
DER Facility ID: 85948
Site ID: 96129
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401

Spill Date: 2000-04-10
Investigator: JHOCONNE
Referred To: Not reported
Reported to Dept: 2000-04-10
CID: 389
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-04-10
Spill Record Last Update: 2002-01-23
Spiller Name: CALLER
Spiller Company: CON ED
Spiller Address: 4 IRVING PL
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL Con Ed e2mis #130835 Notes: 4-10-00 1230hrs 1qt dielectric fluid leaked from 3W-1W joint onto 200gal water. Sample taken. Pending results. 1745hrs LSN 00-03462 <1ppm PCB 4-11-00 1200hrs Blown joint found in structure. 4-13-00 1400hrs Cleanup completed by double washing with slix. Liquids removed by tanker, solids by vactor. No leaking equipment. No sump. 10-2-01 1050hrs Blown joint on fdr was cut and removed by #9 on 4/13/00."

Remarks: "caller reporting a spill on 100 gal of water faulty equip lead to spill in a manhole coned#130835 samples taken clean up pending 3way /1 way cable joint leak no callback necessary"

All Materials:

Site ID: 96129
Operable Unit ID: 822162
Operable Unit: 01
Material ID: 288646
Material Code: 0541A
Material Name: dielectric fluid
Case No.: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material FA:	Petroleum
Quantity:	1.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported